L Number	Hits	Search Text	DB	Time stamp
1	27723	(camera video) and (imag\$3 photo\$6 picture) and (surve\$6	USPAT;	2003/07/09 12:49
.	,	superv\$6 monitor\$3 secur\$4) and (car mobile automo\$4	US-PGPUB;	
		vehic\$3)	EPO; JPO;	
			DERWENT;	
			IBM_TDB	
2	16639	((camera video) and (imag\$3 photo\$6 picture) and (surve\$6	USPAT;	2003/07/09 12:49
		superv\$6 monitor\$3 secur\$4) and (car mobile automo\$4	US-PGPUB;	
		vehic\$3)) and (alarm\$3 alert\$3 sound\$3 notif\$5 action\$3)	EPO; JPO;	
			DERWENT;	
			IBM_TDB	0000007100 40 50
3	2627	(((camera video) and (imag\$3 photo\$6 picture) and (surve\$6	USPAT;	2003/07/09 12:50
		superv\$6 monitor\$3 secur\$4) and (car mobile automo\$4	US-PGPUB;	
		vehic\$3)) and (alarm\$3 alert\$3 sound\$3 notif\$5 action\$3)) and	EPO; JPO; DERWENT;	
		(key door window trunk hood) near6 (open clos\$3 lock\$3	IBM_TDB	
_	2052	unlock\$3 ignition) ((((camera video) and (imag\$3 photo\$6 picture) and (surve\$6	USPAT;	2003/07/09 12:54
4	2053	((((camera video) and (inlag\$5 photo\$6 picture) and (surve\$6 superv\$6 monitor\$3 secur\$4) and (car mobile automo\$4	US-PGPUB;	2003/01/09 12.54
		vehic\$3)) and (alarm\$3 alert\$3 sound\$3 notif\$5 action\$3)) and	EPO; JPO;	
		(key door window trunk hood) near6 (open clos\$3 lock\$3	DERWENT;	
		unlock\$3 ignition)) and (phone telephone email e-mail\$3	IBM_TDB	
		pag\$3)	15155	
5	1886	(((((camera video) and (imag\$3 photo\$6 picture) and (surve\$6	USPAT;	2003/07/09 12:54
Ĭ	1000	superv\$6 monitor\$3 secur\$4) and (car mobile automo\$4	US-PGPUB;	
		vehic\$3)) and (alarm\$3 alert\$3 sound\$3 notif\$5 action\$3)) and	EPO; JPO;	
		(key door window trunk hood) near6 (open clos\$3 lock\$3	DERWENT;	
		unlock\$3 ignition)) and (phone telephone email e-mail\$3	IBM_TDB	
		pag\$3)) and (situation condition status)	_	
6	1886	((((((camera video) and (imag\$3 photo\$6 picture) and (surve\$6	USPAT;	2003/07/09 12:55
		superv\$6 monitor\$3 secur\$4) and (car mobile automo\$4	US-PGPUB;	
		vehic\$3)) and (alarm\$3 alert\$3 sound\$3 notif\$5 action\$3)) and	EPO; JPO;	
		(key door window trunk hood) near6 (open clos\$3 lock\$3	DERWENT;	
		unlock\$3 ignition)) and (phone telephone email e-mail\$3	IBM_TDB	
		pag\$3)) and (situation condition status)) and (camera video)		0000/07/00 40 55
7	603	(((((((camera video) and (imag\$3 photo\$6 picture) and	USPAT;	2003/07/09 12:55
		(surve\$6 superv\$6 monitor\$3 secur\$4) and (car mobile	US-PGPUB;	
		automo\$4 vehic\$3)) and (alarm\$3 alert\$3 sound\$3 notif\$5	EPO; JPO; DERWENT;	
		action\$3)) and (key door window trunk hood) near6 (open clos\$3 lock\$3 unlock\$3 ignition)) and (phone telephone email	IBM_TDB	
		e-mail\$3 pag\$3)) and (situation condition status)) and (camera	IDM_IDD	
		video)) and interior		
8	486	(((((((camera video) and (imag\$3 photo\$6 picture) and	USPAT;	2003/07/09 12:55
١	700	(surve\$6 superv\$6 monitor\$3 secur\$4) and (car mobile	US-PGPUB:	2000/01/00 12:00
		automo\$4 vehic\$3)) and (alarm\$3 alert\$3 sound\$3 notif\$5	EPO; JPO;	
		action\$3)) and (key door window trunk hood) near6 (open	DERWENT;	
		clos\$3 lock\$3 unlock\$3 ignition)) and (phone telephone email	IBM_TDB	
		e-mail\$3 pag\$3)) and (situation condition status)) and (camera	_	
		video)) and interior) and inside		
9	480	((((((((camera video) and (imag\$3 photo\$6 picture) and	USPAT;	2003/07/09 12:56
		(surve\$6 superv\$6 monitor\$3 secur\$4) and (car mobile	US-PGPUB;	
		automo\$4 vehic\$3)) and (alarm\$3 alert\$3 sound\$3 notif\$5	EPO; JPO;	
		action\$3)) and (key door window trunk hood) near6 (open	DERWENT;	
		clos\$3 lock\$3 unlock\$3 ignition)) and (phone telephone email	IBM_TDB	
		e-mail\$3 pag\$3)) and (situation condition status)) and (camera		
		video)) and interior) and inside) and (vehic\$3 car mobile		
10		automo\$3)	LICDAT	2002/07/00 42:00
10	218	(((((((camera video) and (imag\$3 photo\$6 picture) and	USPAT;	2003/07/09 13:00
ļ		(surve\$6 superv\$6 monitor\$3 secur\$4) and (car mobile	US-PGPUB;	
ľ		automo\$4 vehic\$3)) and (alarm\$3 alert\$3 sound\$3 notif\$5	EPO; JPO; DERWENT;	
		action\$3)) and (key door window trunk hood) near6 (open	IBM TDB	
		clos\$3 lock\$3 unlock\$3 ignition)) and (phone telephone email e-mail\$3 pag\$3)) and (situation condition status)) and (camera	םם ו_ואוםו	
		video)) and ((interior inside) near10 (vehic\$3 mobile car		
		automo\$3))		
		automoyoj)	L	

(surve\$6 superv\$6 monitor\$3 secur\$4) and (car mobile automo\$4 vehic\$3)) and (alarm\$3 alert\$3 sound\$3 notif\$5 action\$3)) and (key door window trunk hood) near6 (open clos\$3 lock\$3 unlock\$3 ignition)) and (phone telephone email IBM_TDB					
video)) and ((interior inside) near10 (vehic\$3 mobile car automo\$3))) and (message voice aud\$5 verbal\$3 speech\$3)	11	208	(surve\$6 superv\$6 monitor\$3 secur\$4) and (car mobile automo\$4 vehic\$3)) and (alarm\$3 alert\$3 sound\$3 notif\$5 action\$3)) and (key door window trunk hood) near6 (open clos\$3 lock\$3 unlock\$3 ignition)) and (phone telephone email e-mail\$3 pag\$3)) and (situation condition status)) and (camera video)) and ((interior inside) near10 (vehic\$3 mobile car	US-PGPUB; EPO; JPO; DERWENT;	2003/07/09 13:01